CORRECTIONS & UPDATES

Atmel AVR Micro Programmer
September 2001, p. 52, 010005-1
The author has come up with another new release of the software, which may be downloaded free of charge from our website. The old version contained a bug causing incorrect programming of the last few bytes in the 4K device (4051).

Minimalist Induction-Balance Metal Detector
October 2003, p. 60, 020290-1
Unfortunately a few mistakes have been made in the numbering of three ICs on PCB 020290-1. This affects the component overlay of the board (Figure 2).

Position IC1 on the printed circuit board should be IC4 (LM317).
Position IC2 on the printed circuit board should be IC1 (7555).
Position IC4 on the printed circuit board should be IC2 (7555).

DDS RF Signal Generator
October 2003, p. 14, 020299-1
The values of R7 and R8 should be interchanged in the schematic and the parts list.
The correct descriptions are: R7 = 86Ω6; R8 = 43Ω2.